

CHECKLIST

- Use a stable tripod
- Align the camera sensor parallel to the test chart
- Use uniform and good illumination of the test chart
- Clean your lens, remove existing filters
- Deactivate image stabilization of the lens or camera if possible
- Activate the mirror lock-up if available
- Use a self-timer (at least 5 seconds) or a remote release
- Focus on the central Siemens star